



GHOST REMOVER SCREEN (SSC003)

Main Characteristics

Product Characteristics

Paste/Light Brown colour

Instruction for use

- Clean off all ink residue prior to stencil removal.
- Remove stencil with recommended Screenstrip Powder (SST002)
- Apply a small amount of Ghots Remover Screen (SSC003) to both side of the wet mesh with a brush, thoroughly covering the stained areas in a circular motion.
- Leave to stand for 10–15 minutes. If left to stand for longer periods, Ghots Remover Screen can damage the fibres of the mesh.
- Rinse off residue with gently water spray.
- Remove stain with high pressure stripper.

Important

- Stir well before use.

Features

- Use in the screen printing industry for effective removal of hazes and ghost images commonly after left stencil reclaiming.
- Fast acting and highly effective at removing ghost images and stain on all types of mesh.
- May also be used to degrease and chemically abrade new or used aluminum frames perior to mesh stretching.

Standard Packing

1 Kg

Safety and Handling

- Is free from any toxic, carcinogenic, mutagenic and reprotoxic chemicals.
- Does not have a flashpoint and is, therefore, exempt from the Highly Flammable Liquid Regulations.
- SSC003 should be used with care. Wear suitable PPE, for example, appropriate gloves and safety glasses.
- Should be stored away from children.
- Comprehensive information on *the Safety and Handling of Ghost Remover Screen* in Chaiyaboon Material Safety Data Sheet.

Storage

- Ghost Remover Screen should be stored in a cool dry place at 20–25 °C.
- SSC003 be stored for 24 months.



CHAIYABOON
— inKnovation —